
#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

# WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-028473

Address: 333 Burma Road **Date Inspected:** 24-Sep-2012

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1730 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

**CWI Name: CWI Present:** Yes No As noted below. **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

**Bridge No:** 34-0006 **Component:** OBG

### **Summary of Items Observed:**

Quality Assurance Inspector (QA) William Clifford was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

### In Process Visual Inspection

This QA observed, at random intervals, an ABF/JV qualified welder, Rick Clayborn #2773, performing Shielded Metal Arc Welding (SMAW) with 3.2mm diameter E7018-MH4-R electrode and implementing Caltrans approved Welding Procedure Specification (WPS) ABF-WPS-D15-1004-R. Welding was performed on the 20mm butt weld at 13W-pp124.5-W5-DAH.

This weld is a Seismic Performance Critical Member (SPCM) member.

During welding, ABF Quality Control (QC) Pat Swain was noted monitoring the welding parameters.

Dimensions of the repair excavations are as follows:

Y = 1650 mm

L=50mm

W = 20

D=8mm

This QA observed, at random intervals, an ABF/JV qualified welder, Rick Clayborn #2773, performing continued Shielded Metal Arc Welding (SMAW) with 3.2mm diameter E7018-MH4-R electrode and implementing Caltrans approved Welding Procedure Specification (WPS) ABF-WPS-D15-1004-R. Welding was

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

performed on the 20mm butt weld at 12W-pp116.5-W5-DAH.

This weld is a Seismic Performance Critical Member (SPCM) member.

During welding, ABF Quality Control (QC) Pat Swain was noted monitoring the welding parameters.

### **ESW RWR Tracking**

This QA was instructed by Task Leader Bill Levell to generate a spread sheet for the tracking of Request for Weld Repair (RWR) forms submitted by ABF for the repair of Electroslag Welds located at the base of the Tower. This assigned task requires review of all submitted RWR's as well as review of approved QA TL-6031 report forms applicable to this welding, testing, and repair. This QA used the balance of time not allocated for in-process inspection and testing to work on this task.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### **Summary of Conversations:**

Conversations were relevant to work performed.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas (916) 764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Clifford, William	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer